

DIAGNOSTICS TECHNICAL SERVICE BULLETIN



New version now available:

- H36 version Hx1-12-0x
- H46 version Jx2-09-0x

New diagnostic tool software released

A new software update for all ATEQ devices has been released today, including updates for the H46 and H36 tools. The update includes new OE coverage, improved programmable sensor coverage, as well as new functionalities and corrections. Customers are advised to update their diagnostic tools at their earliest convenience.

Improvements and fixes:

- All tools: Bug fixing
- H36 and H46: Keyfob testing has been improved
- H46: Pressing “C” for a long time brings back to the main menu. Same as the VT56.
- H46: Toyota Unlock ECU button has been added.

New content for Europe:

- New OE sensor coverage for: Abarth/Fiat 500-60th; Audi A8/S8 (D5); BMW X3 (G01); Citroen C3 Aircross; Ferrari 812 Superfast; Hyundai Kona; Kia Stinger and Stonic; Land Rover Range Rover Vogue, Nissan Juke 2; Opel/Vauxhall Grandland X; Seat Arona and Ibiza 5; Skoda Rapid 5; Ssangyong LUVi; Volkswagen Polo 6, T-Roc and Tiguan Allspace
- Updated OE sensor/TPMS information for Fiat Fullback, Kia Cerato, Nissan Juke and X-Trail, Opel/Vauxhall Insignia Sports Tourer, Peugeot Expert 2, Renault Kaptur, Ssangyong Rexton, Volkswagen Phaeton
- New aftermarket sensor coverage for: Schrader EZ-sensor, Alcar by Schrader, Italsensor, Alligator Sens-it, HUF Intellisens, Hamaton EU-Pro/Tyresure T-Pro, Orange Direct Fit EU/Simple Sensor and Mobiletron.
- Fixes: VT46: Toyota C-HR OBD issue is fixed.

New content for North America:

- New 2018 OE sensor coverage for: Alfa Romeo 4C, Giulia; Buick Cascada, Enclave, Encore, Envision, LaCrosse, Regal; Cadillac ATS, CT6, CTS, Escalade, XT5, XTS; Chevrolet Aveo, Bolt EV, Camaro, City Express, Colorado, Corvette, Cruze, Equinox, Express, Impala, Malibu, Silverado, Sonic, Spark, Suburban, Tahoe, Traverse, Trax, Volt; Chrysler 300, Pacifica; Dodge Challenger, Charger, Dart, Durango, Journey; GMC Acadia, Canyon, Savana, Sierra, Terrain, Yukon; Jeep Cherokee, Compass, Grand Cherokee, Patriot, Renegade, Wrangler; Ram Promaster, and Truck series.
- Updated 2012-2017 OE sensor/TPMS information for: Audi A3, S3, Allroad Quattro, A8, S8, Q3, Q5, Q7; BMW 3 Series, M2, X3, X4, X5; Buick Lacrosse; Cadillac XT5; Chevrolet City Express, Malibu; Ford F-Series (Super Duty); Genesis G80, G90; Honda Civic, CR-V, HR-V; Jaguar XE; Mazda CX-9, MX-5; McLaren 570, 650S, P1; Mercedes B Class, C Class, GL Class, GLA Class, GLE Class, GLK Class, SLK Class; Ram Trucks and Promaster; Toyota Camry, Land Cruiser, RAV4; Volkswagen Beetle, Golf, GTI, Jetta, Passat, Tiguan.

New content for Asia:

- Updated accuracy coverage for Korea